



I5000 PLC OBSOLETE

The Mitsubishi COM6100-P (i5000 PLC) has been officially obsolete by the manufacturer. While Mitsubishi is still accepting special orders for this PLC, current lead times are approximately 250 days.

To support our customers, D&S has purchased additional inventory and plans to continue placing special orders as needed while Mitsubishi still accepts them. We will make every effort to maintain stock availability for as long as possible.

Due to the obsolescence of the COM6100-P, Mitsubishi has discontinued repair services for these units. As a result, D&S is no longer able to send failed PLCs to an authorized Mitsubishi repair facility for repair. If a PLC requires repair, customers will need to locate a qualified local electronics or PLC repair service capable of servicing the unit.

As with other obsolete PLC platforms, customers who are able to source a replacement PLC through third-party channels may send the unit to D&S for programming and configuration services for a standard programming fee.

Please note that D&S will not purchase PLCs from second-hand or surplus marketplaces. Because we cannot verify the authenticity, condition, repair history, or whether a unit may be a counterfeit product, we are unable to guarantee that such equipment meets our quality and reliability standards.

If you have any questions regarding replacement options, inventory availability, or programming services, please contact D&S Technical Support.